



中国民用航空局  
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

维修许可证  
MAINTENANCE ORGANIZATION CERTIFICATE

编号/No. F00100581

单位名称/NAME OF ORGANIZATION:

VSE Aviation Services, LLC.

单位地址/BUSINESS ADDRESS:

Independence Municipal Airport Independence Kansas 67301 USA

经审查，该单位符合中国民用航空规章第 145 部的要求，可以从事如下类别的维修工作：

Upon finding that the organization complies with the requirements of **CHINA CIVIL AVIATION REGULATION(CCAR)** Part 145, the above organization is adequate to accomplish maintenance of the following ratings:

**Component Maintenance**

- ☆ -

本许可证除被放弃、暂停或吊销，在下述期限内将一直有效。

This certificate, unless cancelled, suspended, or revoked, shall continue in effect until:

2023-06-30

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2018-12-27

再次颁发日期/DATE REISSUED:

2021-06-17





中国民用航空局  
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

## 许可维修项目 LIMITATION OF MAINTENANCE ITEMS

**限定/LIMITATION:**

对第 F00100581 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. F00100581  
is/are limited to the following:

**LOCATION: Independence Kansas**

**Inspection, Repair, Overhaul and Modification of the following Components:**

**Airborne Auxiliary Power (ATA-49):** Limit to 4930 APU Engine Fuel and Control; 4940 APU Start/Ignition System; 4950 APU Bleed Air System; .

**Propeller/Propulsors (ATA-61):** Limit to 6120 Propeller Controlling System.

**Engine Fuel and Control (ATA-73):** Limit to 7310 Engine Fuel Distribution; 7311 Engine Fuel/Oil Cooler; 7312 Fuel Heater; 7313 Fuel Injector Nozzle; 7320 Fuel Controlling System; 7321 Fuel Control/Turbine Engines; 7322 Fuel Control/Reciprocating Engines; 7330 Engine Fuel Indicating System; 7331 Fuel Flow Indicating.

**Ignition (ATA-74):** Limit to 7410 Ignition Power Supply; 7411 Low Tension Coil; 7412 Exciter.

**Air (ATA-75):** Limit to 7510 Engine Anti-Icing System; 7520 Engine Cooling System; 7530 Compressor Bleed Control; 7531 Compressor Bleed Governor; 7532 Compressor Bleed Valve.

**Engine Oil (ATA-79):** Limit to 7910 Engine Oil Storage (Airframe Furnished); 7920 Engine Oil Distribution (Airframe Furnished); 7921 Engine Oil Cooler; 7930 Engine Oil Indicating System; 7931 Engine Oil Pressure.

Detail as listed in CAAC approved maintenance capability list.

- ☆ -

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2012-12-27

再次颁发日期/DATE REISSUED:

2021-06-17

